

U. S. Officials Only  
CONFIDENTIAL

CENTRAL INTELLIGENCE AGENCY  
**INFORMATION REPORT**

25X1A

COUNTRY Tanganyika

SUBJECT Port Information, Dar-Es-Salaam

PLACE ACQUIRED  
(BY SOURCE)DATE ACQUIRED  
(BY SOURCE)

DATE (OF INFO.)

REPORT NO. 

RESPONSIVE TO	
1	2
CD NO.	
DD/C NO.	
ORR NO.	
DAS NO.	
OCI NO.	

DATE DISTR. 9 Jun 54

NO. OF PAGES 1

NO. OF ENCLS.

SUPP. TO  
REPORT NO.

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES. WITHIN THE MEANING OF TITLE 18, SECTION 702 AND 704, OF THE U.S. CODE, AS AMENDED. ITS TRANSMISSION OR REVELATION OF ITS CONTENTS TO OR RECEIPT BY AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW. THE DISSEMINATION OF THIS REPORT IS FACILITATED

THIS IS UNEVALUATED INFORMATION

SOURCE Officer of a US merchant ship.

The Office of Naval Intelligence furnished the following information to CIA for IAC dissemination in accordance with paragraph 3c of NSCID #7. This information was obtained by DIO-3ND and was forwarded as GMI report 38-54-7.

1. Hydrography: The dredging of the main channel has been completed and it now has a depth of 25 feet at mean low water. The channel between north and south reefs has been dredged and the middle shoal has been removed. In the inner harbor, the center shoal and Kurasini shoal have also been dredged, and the water is now 25 feet deep over both shoals. The sunken drydock off East Ferry Point is being removed. In spite of the dredging and clearing operations, large vessels entering or leaving the harbor should continue to stem the tide in making the sharp turn at Ferry Point.
2. Wharf Under Construction: A new wharf is under construction from the mouth of Kurasini Creek southeast to the southeast end of the Lighter Building and Repair Yard. The wharf will be 1800 feet long and will be able to berth three large ocean-going ships. The dredging alongside the wharf has already been completed and there will be 30 feet of water alongside at mean low springs. The first berth is expected to be completed about January 1955, while the remaining berths will probably not be ready until long afterwards due to the slow progress of construction. Apparently the difficulty lies in a lack of adequate supervision over the native labor. The Lighter Building and Repair Yard will be moved to the present location of the Dhow Repair Yard on the west bank of Southern Creek about where a seaplane anchorage was once located.

-end-

756.54	14'
756.548	14'
756.55	14'
756.543	14'
756.534	14'

U. S. Officials Only  
CONFIDENTIAL

DISTRIBUTION	STATE	ARMY	NAVY	AIR	FBI			
--------------	-------	------	------	-----	-----	--	--	--

This report is for the use within the USA of the Intelligence components of the Departments or Agencies indicated above. It is not to be transmitted overseas without the concurrence of the originating office through the Assistant Director of the Office of Collection and Dissemination, CIA.

ONI DECLASSIFICATION/RELEASE INSTRUCTIONS ON FILE